

Fluid Equipment Co., Inc.

70 Mt. Creek Trail
Social Circle, GA 30025
770-787-0551 F8052 Cell 404-386-1499

donmcpeak@att.net

These pump and system control valves had an unusual set-up. The system did not have a building over the installation. So, when the system was not being used the water had to be drained. The 3 pump control valves were normal with opening and closing speed, dual limit switch, solenoid, check feature. The two pressure reducing valves were in parallel (6" X 2"), with dual limit switch. The sixth valve was a pressure relief / drain valve. When the pumps were off, it drained the system.

